



# LOTUA






YNOTM.109  
v.3.0




MONTAGE - ASSEMBLING - MONTAJE





## MODULES
















- Desserrez la vis d'environ 5 tours max.
- Loosen the screw about 5 turns max.
- Aflojar el tornillo unas 5 vueltas max.













-Desserrez la vis d'environ 5 tours max.  
 -Loosen the screw about 5 turns max.  
 -Aflojar el tornillo unas 5 vueltas max.















-Desserrez la vis d'environ 5 tours max.  
 -Loosen the screw about 5 turns max.  
 -Aflojar el tornillo unas 5 vueltas max.












**G**





**H**


Page 5  
Página 5




Page 4  
Página 4

**I**






**D**




-Desserrez la vis d'environ 5 tours max.  
 -Loosen the screw about 5 turns max.  
 -Aflojar el tornillo unas 5 vueltas max.



**E**


-Desserrez la vis d'environ 5 tours max.  
 -Loosen the screw about 5 turns max.  
 -Aflojar el tornillo unas 5 vueltas max.



**G**

4mm


4mm



I




J



3




K





-Desserrez la vis d'environ 5 tours max.  
-Loosen the screw about 5 turns max.  
-Aflojar el tornillo unas 5 vueltas max.


L



M



N




O







P






### FIXATION AU SOL FIXING TO THE FLOOR FIJACION AL SUELO



### NIVELATION DES PIEDS FOOT LEVELING NIVELACION DE LAS PATAS






A




B



-Desserrez la vis d'environ 5 tours max.  
 -Loosen the screw about 5 turns max.  
 -Aflojar el tornillo unas 5 vueltas max.




C



D





**3 Kg**

**Charge Maximale  
Maximum weighth  
Peso maximo**

